T

CASCADE

Technical Tip

B-STDX WAN Switching Platform

Technical Tip Number: 0080

Priority: Normal
Product Change Classification: B

Description: This Technical Tip addresses a problem where a CP crashes when it receives a Telnet attempt while load balancing a circuit.

Status: Active

Solution Number: S96-1152

Originator: Peter Morin

Advanced Support Contact: Larry Byczynski

Component	Version
NMS (UNIX)	N/A
NMS (DOS)	N/A
STDX Firmware	N/A
B-STDX Firmware	CP: pre- 4.1.4 IOP Type A: N/A IOP Type B: N/A

Released: December 20, 1996

Tip Number: 0080.ext

Problem Description

A CP crashes when it receives a Telnet attempt while load-balancing a circuit.

Recommendation

Since it is difficult to determine when a switch is performing load-balancing of a circuit, Cascade recommends that you avoid telneting into a switch until the appropriate fix has been applied. This problem has been corrected in firmware revisions 4.1.4, 4.1.52, and later.

The Cascade logo is a trademark of Cascade Communications Corp.

All other product names are trademarks or registered trademarks of their respective companies.