Product Change Notification: XBee-PRO 868 Firmware Update

Overview of Change	On Dec. 12, 2008 the XBee-PRO 868 module production firmware was changed from 1x22 to 1x23. New revisions will be in stock and begin shipping on Dec. 30, 2008. Details: - 1x23 is backward-compatible with 1x22. An XBee network with a mixture of old firmware (1x22) and new firmware (1x23) will operate seamlessly with no changes required. - 1x23 offers a bug fix regarding the Loopback Cluster ID, and adds XBee Adapter support features to 1x22. - For customers who wish to test the new firmware 1x23, it is available immediately for download by using X-CTU > Modem Configuration tab > Download new versions… button > Web. - More details can be found on our Support site at http://www.digi.com/support/productdetl.jsp?pid=3553&osvid=0&s=386&tp=2, including: - Firmware revision history - Firmware download - Instructructions for downloading and installing new firmware

Product PN's Affected	*Effective Date*	*Pricing Changes*	*New Revision*	*Hardware Changes*	*Software Change*	*Other*
XBP08-DK	*12/12/2008*	*None*	*B*	*None*	*1x23 firmware*	*NA*
XBP08-DPSIT-024	*12/12/2008*	*None*	*B*	*None*	*1x23 firmware*	*NA*
XBP08-DPSUT-024	*12/12/2008*	*None*	*B*	*None*	*1x23 firmware*	*NA*
XBP08-DPWIT-024	*12/12/2008*	*None*	*B*	*None*	*1x23 firmware*	*NA*