

## Install Software




Note: Microsoft Windows may indicate that the JTAG Link driver is not digitally signed. Please click "Continue Anyway" to complete the installation of the software.

Connect Wi-EM™  
Connect EM™




## Connect Hardware to Development Board



Tip: You may defer connecting the hardware until you are ready to test your application.


## Connect JTAG Adapter to Module

Connect USB JTAG link debugger to P4 connector on development board.



Orient tab on connector to tab printed on development board. JTAG link debugger ribbon is highlighted to line up with pin 1.

## Connect USB JTAG Debugger to USB Port



**Congratulations,**  
Your hardware installation is complete. Return to the Welcome screen from the software installation and click the Getting Started link.



**IMPORTANT!** You must install the software before connecting the Digi JTAG Link Debugger.

